

Ingraffia Home Inspections

PROFESSIONAL HOME INSPECTION

24171 Hollyoak #D, Aliso Viejo, CA 92656

SUMMARY NOTES

CLIENT

Clients Name

PROPERTY

Property Address

Property Address

Approximate Year Built: 1980

Construction Type: Stucco/Brick

BUYERS AGENT

Agents Name

Agents Profession & Company

INSPECTION DATE

11/13/2009

78°F

Electrical - Interior

Note Number: F-01.11a

exposed wiring between the two garage doors was observed. The wiring hanging is live and should be mounted in a junction box. Recommend that a licensed electrician perform the work.



Heating & Air Conditioning

General Note:

The gas line in the attic that supplies the heater is leaking at the elbow. Notice the white paste at the elbow in the picture.

